

Services Officer

23 March 1949

Chief, FBIB

Alterations and Repairs to New FBIB Quarters, South Building

Ref. : Memorandum to Services Officer from Chief, FBIB dated 11 March 1949  
subject as above.

In view of information received by FBIB to the effect that the Telephone Section, CIA will require the use of Room 353 South Building, it is requested that the following changes be made in reference above.

1. To paragraph b. Second Floor

Add: "Install monitoring booths in rooms 240 and 242 in accordance with Substitute Attachment B."

2. From paragraph c. Third Floor

Delete: Sub paragraph 5.

L. K. WHITE

Attachment  
Substitute  
Attach. B

JRC/dt

This document is part of classified integrated file.  
If separated from file, document is unclassified.

0010100

STAT

780100

0010100